[Sep-2020High Quality Braindump2go 300-615 Exam Dumps VCE 300-615 85Q Free Share[Q31-Q46

2020/Sep Latest Braindump2go 300-615 Exam Dumps with PDF and VCE Free Updated Today! Following are some new 300-615 Real Exam Questions!QUESTION 31An attempt to use a global vNIC redundancy template pair results in a service profile that fails to apply. Which action resolves the issues?A. Create the peer names before creating the templates.B. Assign the secondary template first, and then set the peer name.C. Assign both templates simultaneously.D. Assign the primary template first, and then set the peer name. Answer: DQUESTION 32An engineer attempts to register Cisco UCS Manager to Cisco UCS Central, but the registration fails. The engineer can ping Cisco UCS Central from UCS Manager. Which two actions must the engineer attempt to resolve the problem? (Choose two.)A. Synchronize the date and time to NTP for Cisco UCS Central and the Cisco UCS domains. B. Apply the UCS Central license to UCS Central.C. Place Cisco UCS Manager on the same subnet as Cisco UCS Central.D. Allow port 443 between Cisco UCS Manager and Cisco UCS Central.E. Allow port 9443 between Cisco UCS Manager and Cisco UCS Central. Answer: ADQUESTION 33You have an ACI environment with three APICs, two spine switches, and four-leaf switches. You wipe and reboot all APICs first then leaf and spine switches one- by-one and successfully go through the Initial Setuo dialogue on the APIC 1 CIMC KVM console. When you log in to the APIC1 WebGUI, you notice that you do not see any directly connected leaf switches being discovered under Fabric > Inventory > Fabric Membership. What is the cause of the issue?A. The leaf nodes were not erased properly, which caused a fabric parameters mismatch with the APIC1.B. Rebooting the APICs and the leaf and spine switches after wiping them is not required.C. You forgot to enter the TEP Pool value during the Initial Setup dialogue on APIC1.D. The same Fabric Name value should be used before after wiping all devices. Answer: CQUESTION 34An engineer must replace a failed memory on a Cisco UCS B-Series Blade Server. After the replacement was done, the server has a "resolve slot" warning. Which server maintenance action resolves the issue?A. Perform diagnostic interrupt on the server.B. Re-acknowlegement the server.C. Reset the server.D. Decomission the server.Answer: BQUESTION 35Cisco Unified Computing System Manager raises a critical error message that indicates that the system has overlapping Ethernet and FCoE VLANs. All of the Ethernet traffic on the overlapping VLANs drops. Which action resolves the issue? A. Modify the VLAN assignment to vNICs.B. Change the PIN groups on the vHBAs.C. Modify the FCoE VLAN.D. Set the FCoE VLAN as the native VLAN on server uplinks. Answer: AOUESTION 36Refer to the exhibit. An engineer is performing a health check on ACI.

Which statement about interface Ethernet 1/11 is true?

Ethernet1/11 is up (out-of-service) admin state is up, Dedicated Interface Hardware: 1000/10000 Ethernet, address: e4aa/5d94.a2b5 (bia e4aa.5d94.a2b5 MTU 9000 bytes, BW 10000000 Kbit, DLY 1 usec reliability 255/255, txload 1/255, rxload 1/255 Encapsulation ARPA, medium is broadcast Port mode is trunk full-duplex, 10 Gb/s, media type is 10G FEC (forward-error-correction) : disable-fec Auto-mdix is turned off Rate mode is dedicated Switchport monitor is off EtherType is 0x8100 EEE (efficient-ethernet) : n/a Last link flapped 4d06h Last clearing of "show interface" counters never 1 interface resets 30 seconds input rate 0 bits/sec, 0 packets/sec 30 seconds output rate 0 bits/sec, 0 packets/sec

A. The interface is working correctly and fully operational, but it is not in use.B. The interface policy is misconfigured.C. "out-of-service" is the default interface status in ACI.D. "out-of-service" indicates that no service graph is in use for this interface. Answer: BQUESTION 37A user reports that they cannot reach from a UCS server to an FC Storage array. Which command is used to test communication between an FCF and a target?A. fcrouteB. tracerouteC. fcpingD. pingAnswer: CQUESTION 38Refer to the exhibit. You configure a vPC between two Cisco Nexus 7000 Series switches but the peer link will not come up. What is the problem?

```
Nexus 1:

vpc domain 10

role priority 1

system-priority 1

peer-keepalive destination 1.1.1.1 source 1.1.1.2

Nexus 2:

vpc domain 10

role priority 2

system-priority 2

peer-keepalive destination 1.1.1.2 source 1.1.1.1
```

A. The configuration is correct. The problem lies elsewhere.B. The vPC domain numbers must be different.C. The role priority must be the same.D. The system priority must be the same.Answer: DExplanation: https://www.cisco.com/c/en/us/products/collateral/switches/nexus-5000-series-switches/configuration_guide_c07-543563.html
QUESTION 39You are configuring a Cisco Nexus 9000 Series Switch. Which configuration can be implemented for VXLAN BGP EVPN?A. VXLAN BGP EVPN by using an NVE interface in a default VRFB. RACLs on the Layer 3 uplinks for the VXLAN trafficC. QoS classification for the VXLAN traffic on all of the interfacesD. DHCP snooping on the VXLAN VLANsAnswer: A Explanation:

https://www.cisco.com/c/en/us/td/docs/switches/datacenter/nexus9000/sw/93x/vxlan/configuration/guide/b-cisco-nexus-9000-series-nx-os-vxlan-configuration-guide-93x/b-cisco-nexus-9000-

series-nx-os-vxlan-configuration-guide-93x_chapter_0101.htmlQUESTION 40Refer to the exhibit. The VXLAN configuration fails.

Which action do you take to resolve the issue? feature nv overlay

```
feature nv overlay
feature vn-segment-vlan-based

vlan 500
  vn-segment 5500

interface loopback1
  ip address 10 1.1 1/24
  vp router ospr 10 1 1/24
  ip pim sparse-mode

interface nve1
  no shutdown
  source-interface loopback1
  overlay-encapsulation VXLAN
  member vni 5500 mcast-group 239.1.1.1
```

A. Change the multicast address in the 232.0.0.0/8 range.B. Change the mask of loopback1 to 255.255.255.255.C. Use a transit interface as the source interface.D. Enable dense mode on loopback1.Answer: BQUESTION 41Refer to the exhibit. The HSRP instance on both switches is showing as active.Which action resolves the issue?

```
N9K-A
                                interface Vlan100
interface Vlan100
                               ip address 10.10.100.195/26 ip router eigrp 50
ip address 10.10.100.194/26
ip router eigrp 50
ip passive-interface eigrp 50 ip passive-interface eigrp 50
                                hsrp 100
hsrp 100
authentication text pa$$word
                               authentication text pa$$word
                                preempt
preempt
                                priority 120
priority 150
                                timers msec 300 msec 1500
 timers msec 500 msec 1000
                                ip 10.10.100.193
ip 10.10.100.193
 WWW.Br
N9K-A# sh hsrp brief
 *: IPv6 group #:group belongs to a bundle
                         P indicates configured to preempt.
Interface Grp Prio
                         P State Active addr Standby addr
 Vlan100
           100
                  150
                         P Active local
                                                 unknown 10.10.1
N9K-B# sh hsrp brief
 *: IPv6 group #:group belongs to a bundle
                          P indicates configured to preempt.
Interface Grp Prio
                         P State Active addr Standby addr Gr
P Active local unknown 10.10.10
 Vlan100
          100
                 120
```

Configure the HSRP timers to be the same.B. Allow VLAN 100 between the switches.C. Configure the IP address of N9K-B on the same subnet as N9K-A.D. Configure preempt on only one of the switches. Answer: BQUESTION 42An engineer is troubleshooting a fabric discovery failure. Which two requirements must an engineer verify about switch connectivity to solve the problem? (Choose two.)A. A Cisco APIC must be attached to a spine node only.B. A Cisco APIC must be attached to leaf nodes. Spine nodes must connect to other spine nodes.D. A Cisco APIC must be dual-attached to two separate spine nodes.E. Leaf nodes must connect to spine nodes only. Answer: BEQUESTION 43Refer to the exhibit. A network engineer has connected the Nexus switch management port to the Internet using DHCP to allow the Guest shell running on the switch to download Python packages. The engineer can ping google.com successfully from the Nexus switch, but the Guest shell failed to download any Python

packages. Which action resolves the problem?

```
vrf context management
  ip name-server 4.2.2.2
  ip route 0.0.0.0/0 192.168.30.2
 interface mgmt0
  ip address dhcp
  vrf member management
 N9K-Core# ping google.com vrf management
 Pt. ( ) / (m n ) 6 5 2 7 ( E) 6 f ( ) 64 bytes from 216.58.209.238: icmp_seq=0
 64 bytes fron 216.58.209.238: icmp_seq=1 ttl=127 time=136.198 ms
 64 bytes fron 216.58.209.238: icmp_seq=2 ttl=127 time=224.796 ms
 64 bytes fron 216.58.209.238: icmp_seq=3 ttl=127 time=148.458 ms
 64 bytes fron 216.58.209.238: icmp_seq=4 ttl=127 time=129.98 ms
   - - google.com ping statistics - - -
 5 packets transmitted, 5 packets received, 0.00% packet loss
 round-trip min/avg/max = 129.98/158.282/224.796 ms
```

Update the Python packages on the Cisco Nexus switch directly.B. Manually configure DNS in the Guest shell, even if it is claimed on the Cisco Nexus switch through DHCP.C. Manually configure NTP in the Guest shell.D. Connect Guest shell to data plane interfaces to be able to connect to the networks outside the Cisco Nexus switch. Answer: BQUESTION 44Refer to the exhibit.

vPC between switch1 and switch2 is not working. Which two actions are needed to fix the problem? (Choose two.)

```
switch1# show vpc brief
Legend:
(*) - local vPC is down, fo
vPC domain id : 500
Peer status : peer link is vPC keep-alive status : Sus
Configuration consistency s
vPC role : secondary, opera
Number of vPCs configured :
Peer Gateway : Disabled
Dual-active exluded VLANs :
vPC Peer-link status
id Port Status Active
Legend:
(*) - local vPC is down, fo
Peer status : peer link is
vPC keep-alive status : Sus
Configuration consistency s
vPC role : secondary, opera
Number of vPCs configured :
Peer Gateway : Disabled
Dual-active exluded VLANs
vPC Peer-link status
id Port Status Active
1 Po500 down -
```

A. Match vPC domain ID between the two devices.B. Configure IP address on the interface.C. Activate VLANs on the vPC. Configure vPC peer link and vPC peer keepalive correctly.E. Configure one of the switches as primary for the vPC.Answer: ACQUESTION 45Refer to the exhibit. Sw1 and Sw2 are two Cisco Nexus 9000 Series Switches that run Cisco NX-OS. They are VTEPs in the same vPC domain. Which statement describes what happens in this scenario?

```
Swl(config) # sh ip mroute
IP Multicast Routing Table for VRF "default"
(*, 239.0.23.89/32), uptime: 6w2d, ip pim nve
    Incoming interface: Ethernet2/2, RPF nbr: 192.168.21.1
    Outgoing interface list: (count: 1)
         nvel, uptime: 2d01h, nve
(9.9.3.12/32, 239.0.23.89/32), uptime: 6w2d, mrib ip pim nve
    Incoming interface: loopback1, RPF nbr: 9.9.3.12
     Outgoing interface list: (count: 1)
www:Braindump2go.con
Sw2# sh ip mroute
IP Multicast Routing Table for VRF "default"
(*, 239.0.23.89/32), uptime: 24w3d, ip pim nve
     Incoming interface: Ethernet2/2, RPF nbr: 192.168.22.1
    Outgoing interface list: (count: 1)
         nvel, uptime: 19wld, nve
(9.9.3.12/32, 239.0.23.89/32), uptime: 24w3d, mrib ip pim nve
    Incoming interface: loopback1, RPF nbr: 9.9.3.12
    Outgoing interface list: (count: 0)
```

A. Sw1 drops all traffic because there is no (S, G) OIF list to encapsulate VXLAN multicast packets and send them out to the underlay network through the uplink interfaces.B. Sw1 performs the VxLAN multicast encapsulation and decapsulation for all traffic associated with the VxLAN VNIs.C. Sw1 and switch 2 perform the VxLAN multicast encapsulation and decapsulation for all traffic associated with the VxLAN VNIs, depending on the hashing.D. Sw2 did not send an IP PIM register to the rendezvous point for the multicast group of the VXLAN VNI.Answer: BQUESTION 46A customer configures HSRP between two data centers that are interconnected with OTV. The configuration succeeds, but traffic between two ESXi virtual hosts on the same site is routed suboptimally through the OTV overlay. Which two actions optimize the traffic? (Choose two.)A. Disable first-hop redundancy.B. Filter HSRP traffic by using a Layer 3 VACL on the OTV edge devices.C. Filter HSRP by using a Layer 2 MAC-list on the ESXi vSwitch.D. Filter HSRP traffic by using a Layer 3 VACL on the ESXi vSwitch.E. Filter HSRP by using a Layer 2 MAC-list on the OTV edge devices.Answer: ABResources From:1.2020 Latest Braindump2go 300-615 Exam Dumps (PDF & VCE) Free Share: https://www.braindump2go.com/300-615.html2.2020 Latest Braindump2go 300-615 PDF and 300-615 VCE Dumps Free Share: https://drive.google.com/drive/folders/1feRQIR1T37PDk2nuwFIpnzVeG-bXMyGc?usp=sharing3.2020 Free Braindump2go 300-615 PDF Download:https://www.braindump2go.com/free-online-pdf/300-615-PDF(38-48).pdf

https://www.braindump2go.com/free-online-pdf/300-615-PDF-Dumps(11-25).pdf

https://www.braindump2go.com/free-online-pdf/300-615-VCE(26-37).pdf

https://www.braindump2go.com/free-online-pdf/300-615-VCE(49-59).pdf

 $https://www.braindump2go.com/free-online-pdf/300-615-VCE-Dumps(60-70).pdfFree\ Resources\ from\ Braindump2go, We\ Devoted\ to\ Helping\ You\ 100\%\ Pass\ All\ Exams!$